

LAND CORNER RECORDATION CERTIFICATE ROEHM
Filing Requirement of Act 74, Mich. P.A. 1970 Ontonagon County
Ontonagon County Remonumentation Corner of 1 LC 5/196

1P

JJT Rec. Date 06/15/99 Time 13:33
 RECORDING FEE: 9.00

For corners in

Ontonagon County Located in: Corner Code #

- | | | |
|-------------------------|---|---------------|
| 1. Public Land Survey | | T51N R40W K-5 |
| | | T R |
| | | T R |
| | | T R |
| 2. Property Controlling | S | T R |
| in Section | S | T R |
| 3. Miscellaneous | S | T R |
| Property in Sec. | S | T R |

**SURVEY &
 REMONUMENTATION**

MAR 23 2000

SECTION

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
 5. Private Claims

I, Joseph C. Domitrovich, in a field survey on June 3, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 (K-5) - CORNER COMMON TO SECTIONS 11, 12, 13 & 14, T51N, R40W

1845 - William A. Burt set a B. Ash post.

6" B. Ash	S42°W	25 links
9" B. Ash	N66°E	23 links

1933 - John Hawley, timbercruiser, noted, in his personal copy of the original field notes, that he recovered what he believed to be the chopped out stump of the original 9" Black Ash B.T. He stated that an 8" squared black ash tree was at the position of the corner, from the stump, and accepted it.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I recovered the squared Black Ash Tree called for by John Hawley. It is now a 10"+ dead stub with grown over blazes on 4 sides. At the record bearing and distance from this tree to where the 9" Black Ash GLO B.T. would have been, I found a rotten mound rising from the swamp. I was unable to determine the species of the mound. 8 feet west of the Corner tree I found a 4" squared and scribed cedar post lying flat in the water.

Distances from the squared tree to recovered corners to the North, South, East and West are reasonable. I accepted the squared Black Ash Tree as the Section Corner. I cut it down and drove an aluminum rod into its hollow stump.

Research on file with County Remonumentation Representative.

PEER GROUP APPROVED

Earl W. Applekamp
 COUNTY REPRESENTATIVE

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: 6-09-99

Corner is a 3/4" x 8" aluminum rod, driven into a Black Ash Stump, with a 3" diameter aluminum cap stamped to read: County Remonumentation; T51N, R40W; S.11, S. 12, S. 13, S. 14; 1999; P.S. 37273. This corner falls in a waist deep cedar/ash swamp with no dry land within 700 feet of it.

Witnesses:

5" Cedar	N63°E	14.24'
12" Cedar	S62°W	2.74'
6" Black Ash	S62°E	9.52'
Steel Sign Post	N22°W	1.33' (to face)
E. 1/4 Cor. Sec. 11	N00°33'31"E	2641.63'
S. 1/4 Cor. Sec. 11	N89°46'19"W	2608.56'

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted.

Signed by

Joseph C. Domitrovich

Date

6/09/99

Surveyor's Michigan License No. 37273

