JUDITH D. ROEHM 12/13/96 Ontonagon County 10:45 LC 4/ 238 JEM Fee: 9.00 Page 1 of 1

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	FIIIN	à kedanement or v	ICI 74, MICH. P.A. 197	U	
For corners in			1		
Ontonagon	Located In:	Corner Code #	,	SURVEY &	s.)
(County)	Located III.	Come Codo #		REMONUMENTATION	N. C.
1. Public Land Survey	T_51N R. T R T R.			MAY 2 2 1997 COMMISSION	
<ul><li>2. Property Controlling in Section</li><li>3. Miscellaneous Property in Sec.</li></ul>	STR STR STR STR			Register of Deeds Stamp & F	ile Number
A Lot No Re	ecorded Plat				
5. Private Claims				ABCDEFGHI	JKLM
			<del></del>	2 - 6 - 5 - 4 - 3	_ { }
				3	
requirements of P.A. 74, Mic conformance with regulations United States Department of that the corner points menti	, in a field survey on chigan P.A. of 1970, the corns and rules therefore as require the interior, Bureau of Land Moned in lines 3, 4 and 5 above or by a Decree of a Court ced below:	er points mentioned in line d in the current manual of lanagement or by a decree were in conformance with	es 1 and 2 above were in survey instructions of the of a Court of Law and /or the rules of the Michigan	4 - 7 - 8 - 9 - 10 - 5 - 6 - 18 - 17 - 16 - 15 - 7 - 8 - 19 - 20 - 21 - 22 - 22 - 22 - 22 - 22 - 22	-1112 -1413
NOTE: Not more than 2	comers, all in the same tow	n and range, may be re	corded	9	
on this certificate		• •		10 30 29 28 27	-26 <del>- 25-</del>
,	•			11	
(V.3/1-3) Meander Cor	mer on West side of Or	ntonagon River Sec	tion 1 & 12	12 31 32 33 34	_3536
TSIN RANW	al monument and accessor			13	
1845 - William A. Burt At 39.70 chains 16" Cedar,	s, 1/4 Comer fell in Rive S 30 <sup>0</sup> E 12 lin		he crossed River and	i set post.	
I found no remains of the contract of the cont	er evidence found and/or m he original comer or ac mer position by single p uth of blazed line to We	cessories. proportionate measu		er:	
	,				
Research on file with C	County Remonumentati	on Representative.			
C. Description of monus	ment for corner and access rebar with a 3" diamete	sories established to pe r aluminum cap stan	nped to read: M.C.; S	sition of the corner: 6.1, S. 12; T51N, R. 40W; 1990 West of West bank of Ontonag	; gon River.
11" Cedar	\$ 41 <sup>0</sup> E	6.26'	ى ئىلىدىدى	Secretary OF	M IC TEMP
8" Cedar	S 59 <sup>0</sup> W	11.69'	PEER GROUP APP	12-11-96	
6" Ash	N 67 <sup>0</sup> W N 58 <sup>0</sup> E	30.55' 15.91'	all W Cools	kaup 1000	SPH TO
5" Basswood Steel Sign Post	N 58° E	15.91	COUNTY BALLESEN	THE DOMITE	OVICH A
SW Comer Sec. 1	S 89 <sup>0</sup> 28' 19" W	2023.90'		LAI SURV	EYOR P
SE Corner Sec. 1	N 89 <sup>0</sup> 28' 19" E	3181.73'		372	73 /58
NOTE: Bearings are	magnetic. Distances a	re to nail in side of v	witness objects unles:	s noted.	
	Nomita -		Date	12/10/96	Assessed to the state of the st
Surveyor's Michigan Lice	07070		·	A CONTRACTOR OF THE PERSON	OF THE PERSON