

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Ontonagon Located In: Corner Code #  
(County)  
1. Public Land Survey T 51N R 40W 006  
T R L3/M-3 ✓  
T R  
T R  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R

SURVEY &  
REMONUMENTATION

MAY 22 1997

COMMISSION

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Joseph C. Domitrovich, in a field survey on December 4, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

(L-3/ M-3) Meander Corner on East side of Ontonagon River. Sections 1 & 12.  
T51N, R40W

A. Description of original monument and accessories and/or subsequent restoration:

1845 - William A. Burt ran West corrected. He intersected the right bank of the Ontonagon River at 36.37 chains West of the Southeast Corner of Section 1 and marked a 16" Hemlock as the Meander Corner.  
8" Sugar N 56° E 21 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Original corner and accessories have been lost due to severe shoreline erosion. The prorated position of the Meander Corner falls in the Ontonagon River. I established a Witness Corner to the Meander Corner at the top of a steep bank on line between section corners and 284.49' East of the prorated position of Meander Corner.  
Corner falls 19' +/- South of a painted line to the East.

Research on file with County Remonumentation Representative.

PEER GROUP APPROVED  
Paul W. Applebaum 12-11-96  
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 5/8" x 48" rebar with a 3" diameter aluminum cap stamped to read: W.C.M.C.; S.1, S. 12; T.51N, R.40W; 1996; P.S. 37273; COUNTY REMONUMENTATION. Corner falls approximately 120' East of the riverbank.

Witnesses:

4" Hard Maple	N 20° E	14.40'
4" Hard Maple	N 80° E	8.55'
4" Hard Maple	S 67° E	26.65'
Steel Sign Post	West	1.02'
4" Soft Maple	N 32° W	29.53'
SW Corner Sec. 1	S 89° 28' 19" W	3105.63'
SE Corner Sec. 1	N 89° 28' 19" E	2100.00'

NOTE: Bearings are magnetic. Distances are to nail in side of witness objects unless noted.

Signed by John C. Domitrovich

Date 12/11/96

Surveyor's Michigan License No. 37273

