

✓  
MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 51 N.R. 41W


Ontonagon COUNTY

DESCRIPTION OF CORNER Meander Corner between Sections 7 - 8

CORNER MONUMENT 1" Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 9/15/65

WITNESSES TO CORNER..... 7" B. Ash (S8NBT) N35°E 17.9'



7" B. Ash (S8NBT) East 18.0'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at site of a squared Cedar Post,  
shown to us by Victor Arcand, R. L. S.  
Corner apparently accepted by State Highway Department.  
Corner lies 122' North of Centerline of M-64.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 2-28-68  
REGISTERED LAND SURVEYOR