

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Ontonagon
(County)

Located In:

Corner Code #

SURVEY &
REMONUMENTATION

MAY 22 1997

COMMISSION

Register of Deeds Stamp & File Number

1. Public Land Survey

T 51N R 41W
T 51N R 40W

M-7
K-7

2. Property Controlling
In Section

S T R
S T R

3. Miscellaneous

S T R

Property in Section

S T R

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2			
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

~~One quarter~~ section corner common to Sections 13, 18, 24, 19, T51N, R41W.

I, John R. Garske, in a field survey on July 17, 19 96,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

In 1845 Austin Burt, U.S. Deputy Surveyor, set a wooden post from which an 8" maple bears S25°W - 25 links (16.50') and a 12"
Lynn - N20°W - 29 links (19.14').

1994± - Survey by Earl Applekamp, RLS, indicates he set a R.R. spike at the corner location.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found the spike set by Earl Applekamp in a survey of Section 19, T51N, 40W. The corner falls at the centerline intersection of
Townline Road with fence lines running east and west. Distances to other corners used north and west along with discussing the
corner position with Mr. Applekamp were used to verify the R.R. spike. This location has been used and accepted and fits local
occupation lines very well.

Record research on file.

PEER GROUP APPROVED

Earl W. Applekamp 8-14-96
COUNTY CLERK

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I established the following reference objects:

P. pole - S07°E - 124.50 feet

8" Aspen - N58°W - 63.23 feet

Set a reference monument consisting of a 2 1/2" aluminum pipe with 3 1/4" aluminum cap stamped: County
remonumentation, T51N, R41W-R40W, R.M., S-13, S-18, S-24, S-19, 1996, R.L.S. 28410, east, 30.15 feet, S66°W, 32.75 feet
with steel sign rail 0.84 feet away.

Another stamped the same as above except S66°W, 32.75 feet with steel sign rail
0.84 feet away.

SEE SKETCH ON BACK

Signed by

John R. Garske

Date

Surveyor's Michigan License No. 28410

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

