

For corners in

ONTONAGON

(County)

Located In:

Corner Code #

1. Public Land Survey

T51NR 42W

L-7

T R

T R

T R

T R

2. Property Controlling In Section

S_____ T_____ R_____

S _____ **T** _____ **R** _____

3. Miscellaneous Property in Sec

S_____ T_____ R_____

S_____ T_____ R_____

4. Lot No. _____, Recorded Plat _____

5. Private Claims

$\frac{1}{4}$ Corner common to Section 13 & 24, T51N R42W.

I, Earl W. Applekamp, in a field survey on May 27, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by S.W. Higgins, U.S. Deputy surveyor, summer of 1846. Set wood post.

ORIGINAL BEARING TREES:

8" White Birch	N30°W	13.20 feet
10" Balsam	S35°E	11.22 feet

PEER GROUP APPROVED

Earl W Applekamp

COURT REPORTER

6-17-58

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. A timber cut line was evident East of the corner.

Corner was re-established by single proportionate measure and on line between opposite Section corners, East & West.

Research a file with the Ontonagon County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2½"X30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T51N R42W, S13, S24, ¼, 1998, P.S. 17610. I established three bearing trees and a steel sign post.

Nail in 9" White Ash N30°W 29.33' - Nail in 7" Maple S43°W 29.20'
Nail in 9" Triple Maple N41°E 41.53' - 6' steel sign post South 0.93'

Signed by Earl W Applekamp
Surveyor's Michigan License No. 17610

Date May 27, 1998

