

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 53 N.R. 38 W


Ontonagon COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 15-22

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 3/24/65

WITNESSES TO CORNER..... 9" Cedar (1/4S NBT), S 17° E, 22 Links



17" Hemlock (1/4S 15/22 NBT), N 80° E, 24 Links

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-established midway and on line between two Section Corners.
Found no evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
BILLY D. BUCKLER
REGISTERED LAND SURVEYOR
DATE April 7, 1965