

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION



LAND CORNER RECORD

T. 53 N. R. 38 W


Ontonagon COUNTY

DESCRIPTION OF CORNER East 1/16 Corner, Section 22

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 3/26/65

WITNESSES TO CORNER..... 13" Hemlock, (E1/16 BT), S 03° W, 51½ Links



13" Hemlock, (1/16 BT), S 47° E, 45 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was established midway between East 1/4 Corner and the Center of Section.
Corner lies in East margin of stream bottom, 50 Links SE of stream.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE April 7, 1965
REGISTERED LAND SURVEYOR