## LAND CORNER RECORDATION CERTIFICATE

		ent of Act 74, Mich.	
For Corners In: Presque Isle	Located In Co	orner Code#	
(County)			
1. Public Land Survey	T 33N R 2E T 33N R 2E		
Property Controlling in Section	S T R		
3. Miscellaneous	S   R		
Property in Section	S T R R		Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:	·	
5. Private Claims:			A B C D E F G H I J K L M
I, <u>Carl T. Kiiskila</u> , in a field survey on <u>May 29, 2008</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			
A. Description of original monument and accessories and/or subsequent restoration:			
I-7 G.L.O. 1851 Geo. H. Cannon set post for corner of K-7 G.L.O. 1851 Geo. H. Cannon set post corner			
sections 14,15,228 Wits: Spruce P	&23. ine 14" N5°W 35 links Pine 12" S75°E 36 links	secs.13,14,2 Wits: S	23&24 Spruce Pine 8" S21°W 27 links Spruce Pine 8" N44°E 39 links
Marcus Schaaf R.L.S. #3104 index shows he set a mon. for the corner while working in the area CIRCA 1940.  Marcus Schaaf R.L.S. #3104 index shows he set a monument for the corner while working in the area CII 1940.			aaf R.L.S. #3104 index shows he set a for the corner while working in the area CIRCA
Liber 314, Page 13, 19 a 2" pipe in the interse Wits: S51°W 17.82' S54°W 30.30' N86°E 15.37' S54°E 14.63'	7" Twin J. Pine 6" J. Pine		
Page 614, 1982 Ronald Bischer P.S.#22423 found			
a 2" pipe.  Wits: N56°W 30.31'  N73°E 19.65  S50°W 17.47	6" Tw. J. Pine 6" Oak		
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:			
	evidence found and/or method applie led 1⁄2" x 18" rod with PS cap #339		ablishing corner: 2 " pipe added ½" x 18" rod with PS cap #33981
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:			
I-7 Placed ½" X 18" rod with PS Cap #33981 in found 2" pipe Wit: Set nail and tag in S side 10" twin J. Pine N54°W 30.13' Set nail and tag in NW side 16" Oak S50°W 17.52' Fd. nail and tag in SW side 8" Oak S25°E 34.36' Set nail and tag in N side 5" Oak N79°E 25.98'  K-7 Placed ½" X 18" rod with PS Cap #33981 in found 2" pipe Wit: Set nail and tag in NE side of a 12" Jack Pine N30°W 14.5  Set nail and tag in NW side of a 14" Jack Pine N69°E 35.0  Set nail and tag in N side of a 6" Jack Pine S73°E 21.4'  Set nail and tag in NW side of a 10" Red Pine S69°W 34.			and tag in NE side of a 12" Jack Pine N30°W 14.96' and tag in NW side of a 14" Jack Pine N69°E 35.00' and tag in N side of a 6" Jack Pine S73°E 21.41'
Signed by:	arl TKiskila	Date:	9-15-08 KIISKILA LAND
Surveyor's Michigan	License No.: 33981		SURVEYOR No. 33981
FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971 Revised May 14, 1975			
Revised Jan. 1983 Revised Oct. 1995			