

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Presque Isle (County) Located In Corner Code #
1. Public Land Survey T R
2. Property Controlling in Section S 23 T 33N R 2E 12
3. Miscellaneous Property in Section S T R
4. Lot No: Recorded Plat:
5. Private Claims:

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M). Contains numbers 1-36 and two dots in row 9, column J.

I, Carl T. Kiiskila, in a field survey on June 11, 2008 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
12- This corner position was not established during the Original Government Survey.
14- Marcus Schaaf R.L.S. #3104 index shows he set a monument for the corner while working in the area CIRCA 1940.
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:
12- Established the Southwest corner of the Northwest quarter of the Southeast quarter of section 23 as per B.L.M. instructions for the subdivision of a section.
14- Found a 2" Pipe fitting the proper position for standard B.L.M. instructions for the subdivision of a section.
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
12- Set a 5/8" X 32" rod with P.S. Cap #33981
Wit: Set a nail and tag in SW side of a 6" J. Pine S66°W 8.78'
Set a nail and tag in SE side of a 8" J. Pine N38°E 16.16'
Set a nail and tag in the S side of a 6" Maple N56°W 15.48'
Set a nail and tag in the East side of a 4" Elm S09°W 18.87'
Found 1 1/2" Pipe S06°W 15.28'
Carsonite Post North 1'±
14- Set 1/2" X 18" iron rod with PS Cap #33981 in found 2" pipe
Wit: Set nail and tag in S side of a 8" Oak N70°W 48.21'
Set nail and tag in NW side of a 8" J. Pine N48°E 38.95'
Set nail and tag in the S side of a 12" R. Pine S56°E 27.09'
Set nail and tag in the W side of a 10" R. Pine S22°E 47.13'
Carsonite post North 1'±

Signed by: Carl T Kiiskila
Surveyor's Michigan License No.: 33981

Date: 9-15-08

