

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Presque Isle
(County)

Located In

Corner Code #

1. Public Land Survey	T	33N	R	4E	E-9
	T		R		
2. Property Controlling in Section	S	20	T	33N	R
	S		T		R
3. Miscellaneous Property in Section	S		T		R
	S		T		R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on May 8, 2002 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

E-9 G.L.O. Alfred Millerd 1855 set section post
Wit: White Pine 20 N60°E 3 links
Cedar 12 S33°W 18 links

9- Norman J. Quaine P.S. #33984 September 1993
certificate of survey shows he set a 1/2" rod and cap #15410
for the corner. No witnesses given.

Page 555, Presque Isle County Land Corner Records,
October 1981 Ronald R. Bischer P.S. #22428 found stake
point and both O.B.T. stumps set 1/2" rod

Wit: N54°E 20.65' 10" Cedar
S06°E 23.97' 10" Cedar
S72°W 56.42' 14" Cedar

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

E-9 Found 1/2" capped iron rod P.S. #15410, set over top a 1" X 48" pipe with a P.S. cap #33981.

9-Found 1/2" rod W / P.S. CAP #15410.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-9 Found 1/2" capped rod, placed 1" X 48" pipe with P.S. cap #33981 over top.

Wit: 14" Cedar N55°E 20.34'
10" Spruce S54°E 10.03'
14" Cedar S04°E 22.83'
8" Tamarack N61°W 44.70'
Blue Carsonite post North 1'±

9- Found 1/2" capped rod P.S. #15410

Wit: 12" Cedar N82°W 22.24'
8" Maple S53°E 19.37'
8" Spruce N10°E 21.98'
8" Cedar S50°W 25.00'
Blue Carsonite post North 1'±

Signed by:

Carl T Kiiskila

Date:

8-26-02

Surveyor's Michigan License No.:

33981

