

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Presque Isle Located In: Corner Code #
(County)

1. Public Land Survey T34NR 5E A-8
T R
T R
T R
T R

2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

PRESQUE ISLE COUNTY
RECORDED

96 JUN -4 AM 11:24

Janet M. Lamb
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Norman J. Quaine in a field survey on Dec. 8, 1995 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

A-8	1856	November 30, 1971
1840	Re-established	Survey recorded in Liber 196 Pg 399
Twp. lines run	Township line by	by Delmer E. Porter LS#15410
by John Hodgson	Alfred Millard	1/2" Rod
Deputy Surveyor	Deputy Surveyor	8" Cedar N23° E 162.21'
Beech 10 S32W 7	Set Quarter	8" Tw Maple N62° E 133.35'
Hem 14 N44E 30	Section Post	T&P Pole S35° E 87.14'
	Hemlock 15 N27E 29	
	Hemlock 20 S48W 13	

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-8
December 8, 1995
Norman J. Quaine PS#33984
Porter's Survey P.C.
1996 P.I. Co. State
Remonumentation

Fd. Conc Mon/Brass Cap
N30° E 65.76' 12" Aspen
S29° E 87.31' P. Pole

LCRC, Sept. 28, 1978
Delmer E. Porter LS#15410
1/2" Rod
N23° E 162.21' 8" Cedar
N62° E 133.35' Tw. Maple
S35° E 87.14' P. Pole

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-8
Left Conc Mon/Brass Cap
N30° E 65.76' 12" Aspen
N66° E 60.39' 7" Aspen
S29° E 87.31' P. Pole
N73° E 89.02' 5" Cedar

Ratified by Peer Group
in accordance with P.A. 345
Chairman *Delmer E. Porter*
Date 5/22/96

LCRC, Nov. 9, 1979
Delmer E. Porter LS#15410
Fd 1/2" Rod
Set Conc Mon & brass cap
N30° E 65.60' 8" Aspen
S35° E 87.19' P. Pole
N85° W 32.40' FE Post
Note: Porter's Survey Wit.
note from office files
indicates S30° E 87.19'
P. Pole. Assumed one or the
other is a scribe's error.

*Witness tags & nails.

Porter's Survey P.C.

Signed by Norman J. Quaine
Surveyor's Michigan License No. 33984

Date MAY 29, 1996