

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
PRESQUE ISLE

(County)

Located In:

Corner Code --#

- | | | |
|------------------------------------|------------|----------|
| 1. Public Land Survey | T 35N R 3E | 1-3, 1-4 |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S 11 T R | 8 |
| | S T R | |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, CARL F. ROSER, in a field survey on JUNE 7, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- I-3 I-4 I-4 CONTINUED

(NO EVIDENCE OF G.L.O. CORNER, B.T.'S, LINE TREES & TOPOGRAPHY, AS CALLED OUT IN THE G.L.O. LINE NOTES; UNLESS NOTED IN ITEM "B" BELOW.)

"B" CONTINUED.
STREAM TIE WAS TO NEAREST 1/2 CH & THEREFORE COULD NOT ISOLATE 63' SHORTAGE IN MILE WITHIN $\pm 33'$. (SEE COR REC 1-8, E1/4 S-22, FOR BACKGROUND ON GLO RESURVEY THIS TWP. I DO NOT THINK A GLO CH TALLY

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I-3
RESTORED NE COR OF SEC 10 (SET 5/8" X 34" REROD W/P.S. CAP #12028) AT POSITION OF CTR OF FD 1" PIPE (HORIZONTAL & BURIED IN GRAVEL ROAD) AND TO FIT TWO 1978 DEL PORTER WITS. PORTER HAD FD 1" PIPE HERE IN 1978. CTR OF N-S GRAVEL ROAD IS EAST 3' \pm . CTR OF COUNTY ROAD LOOKING W'LY IS 6' \pm SOUTH.

I-4
RESTORED 1/4 CORNER COMMON TO SEC'S 10 & 11 MIDWAY BETWEEN FD NE & SE COR'S OF SEC 10 AND ON SPLIT OF N-S R/W FNS TO E & W. N-S, B-W, R/W FNS 21.5' \pm TO E & W. CTR N-S GRAVEL RD IS 6' \pm E. CONSIDERED SETTING COR PER GLO STREAM TIE TO S, GLO 13.50 CHS (891' TO NEAREST 1/2 CH), 906' MEA. DECIDED TO SET S.P. TO GLO FOR 1 MILE (& SPLIT OF R/W FNS) SINCE OLD

I-4 CONTINUED
WAS DROPPED IN E LINE OF SEC'S 10, 15 & 22, BUT THAT THE DIFFERENCE PER MILE IS CUMULATIVE & CONSISTANT, UNLESS IT CAN BE ISOLATED BY GLO TIES TO NEAREST LINK OR 10 LINKS).

B
ESTABLISHED SW COR OF SE 1/4 OF NW 1/4 SEC 11 PER STANDARD BLM INSTRUCTIONS. N-S B.WIRE FENCE IS 447' \pm EAST. E-W B.WIRE FENCE IS 217' \pm SOUTH.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-3
SET 5/8" X 34" REROD W/CAP IN RD INTERSECTION.
FENCE POST S50°W 52.23'
5" CEDAR N52°E 34.43'
10" W PINE N60°W 65.42'
10" SPRUCE N05°W 93.93'
(TOP CUT OFF BY UTIL CO.)
#14" SCOTCH PINE N47°W 51.33'
#6" ELM S39°E 34.22'
#OLD WIT. PORTER #15410

I-4
SET 5/8" X 30" REROD W/CAP 4" BELOW CO RD SURFACE.
10" SPRUCE N12°W 38.69'
3" W PINE S27°W 51.37'
5" BALSAM S39°E 34.67'
SET CED POST W/
LOC TAG EAST 25'
COR FM POST B-W FNS N & E (IS 85.5'S & 22'E) S07°E 88.78'

I-4 CONTINUED

B
DROVE 5/8" X 34" REROD W/RLS CAP. SET CED POST W/LOC TAG.
5" W PINE N15°W 23.87'
3" W PINE N 5°E 14.59'
3" BALSAM N75°E 17.42'
6" W PINE S10°W 17.93'

Signed by Carl F. Roser

Date 6-08-95

Surveyor's Michigan License No. 12028