

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Presque Isle
(County)

Located In

Corner Code #

1. Public Land Survey T R
T R
2. Property Controlling in Section S 20 T 36N R 2E 12
S 20 T 36N R 2E 13
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on August 4, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

12 - CS 1/16 Corner, Section 20, T36N, R2E

13 - SE 1/16 Corner, Section 20, T36N,R2E

None

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

12 - CS 1/16 Corner, Section 20, T36N, R2E

13 - SE 1/16 Corner, Section 20, T36N,R2E

Set stamped 2" dia. Alum. cap on 5/8"x34" rebar per standard BLM procedure. Position falls two feet East of C/L N-S trail road. Found no other evidence to dispute the location for the corner.

Set stamped 2" dia. Alum. cap on 5/8"x34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

12 - CS 1/16 Corner, Section 20, T36N, R2E

13 - SE 1/16 Corner, Section 20, T36N,R2E

Stamped 2" dia. Alum. cap on 5/8"x34" rebar.

Stamped 2" dia. Alum. cap on 5/8"x34" rebar.

Wit: N60°E 31.13' to set N&T on SE side 6" R.Maple
S55°E 29.56' to set N&T on NE side 5" W. Birch
S23°W 28.89' to set N&T on NW side 7" R. Maple
N36°W 20.39' to set N&T on SW side 6" W.Pine
Set Blue Carsonite Post w/ location tag 15' East

Wit: N73°E 20.78' to set N&T on N side 6" R.Maple
S27°E 23.70' to set N&T on SW side 14" W. Pine
N72°W 44.85' to set N&T on S side 13" Hemlock
N16°W 43.98' to set N&T on N side 6" Balsam Fir
Set Blue Carsonite Post w/ location tag 1' North

Carl T Kiiskila

Surveyor's Michigan License No.: 33981

10-8-09

