

2236
COMMISSION LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
PRESQUE ISLE
(County)

Located In:

Corner Code #

1. Public Land Survey T 36N R 2E L-7
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Section S T R

4. Lot No. , Recorded Plat
5. Private Claims

LIBER 316 PAGE 319
PRESQUE ISLE COUNTY
REGISTERED

95 OCT 20 PM 4:35

Janet M. Lamb
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Ronald Bischer, in a field survey on August 7, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO Notes - 1856 Resurvey
Geo H. Cannon
Set Wood Post
W. Pine 12" S05°E 11½ lks
Cedar 10" N71°W 8½ lks

01-30-76 - Ronald R. Bischer
Found 1" Iron Bar
N26°E 86.36' 6" Spruce
S06°E 86.70' Power pole

03-30-78 - Delmar E. Porter #15410
Replaced 1" Iron Bar with ½" Rod in monument box
N26°E 86.36' 6" Spruce
S06°E 86.70' Power pole
S06°W 39.70' Fe. Cor.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" Bar in monument box, replaced 1" Bar with ½" Rod and Cap #22428.
S06°E 86.58' Power pole
N25°E 86.33' 9" Spruce
S05°W 38.60' Fence corner - post leaning over



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

½" Rod and Cap #22428 in monument box
S06°E 86.58' Power pole
N25°E 86.33' 9" Spruce
S20°E 104.20' 7" Spruce
N02°E 83.85' 9" W. Pine

Nails with witness tag #22428 used.

Ratified by Peer Group
in accordance with P.A. 345
Chairman *Delmar E. Porter*
Date 9/20/95

Signed by *Ronald E. Bischer*
Surveyor's Michigan License No. 22428

Date Oct. 3, 1995