

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 23 NR. 2 W. . .

Roscommon COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 28 and 33

DESCRIPTION OF CORNER MONUMENT Left 1 1/4" pipe in place

WITNESSES TO CORNER

10" Balsam - S48W - 24 1/2 links

36" W. Pine Stump - S63E - 53 1/2 links

OBT 30" W. Pine Stump - N15W - 19 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

This corner was found by Forestry Division survey crew while making a survey in this township. Found 1 1/4" pipe in place, previously restored from the government BTs by Marcus Schaaf, Reg. Land Surveyor. NW W. Pine stump in place, scribed OBT, and remains of SE Hemlock.

Corner was witnessed August 19, 1959.

SURVEYORS SEAL

SIGNED Kenneth J. Gilling DATE 8/28/59  
REGISTERED LAND SURVEYOR