

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 23 NR. 2 W.

Roscommon COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 3 and 10

DESCRIPTION OF CORNER MONUMENT Left 1 1/4" pipe in place, 2' above ground

WITNESSES TO CORNER

16" R. Oak - S64E - 93 links
8" Maple - S88W - 102 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was found by Forestry Division Land Surveyor while
searching for corners in this township. Found 1 1/4" pipe in place
as previously restored by Marcus Schaaf, RLS, from original BT.
SE W. Pine stump in place with evidence of face and BM.

Corner was witnessed October 4, 1960.

SURVEYORS SEAL

SIGNED *Timothy J. Reithing* DATE 10/106
REGISTERED LAND SURVEYOR