

4551

SURVEY &
REMONUMENTATION

APR 07 1998

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970For corners in
Roscommon
(County)

Located In:

Corner Code #

STATE OF MICHIGAN
ROSCOMMON COUNTY
RECORDED

SECTION

10 JUL 97 2:15 P.M.

ROBERT W. SMITH
REGISTER OF DEEDSFILE IN LIBER 3 OF LAND CORNERS
Register of Deeds Stamp & File Number

1. Public Land Survey T 23N R 2W F-7
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Section S T R
4. Lot No. , Recorded Plat
5. Private Claims

I, Marvin E. Myers, in a field survey on 12 June, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO - John Brink 1852
Mon. - Post
WIT: 4" Tamarack S38°W 1.26 lks
3" Tamarack N44°E 1.35 lks

DNR - Schaaf - 1935±
Mon. -
Found or established, and replaced

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1½" pipe (typical Schaaf monument) 0.8' above surface of water in good condition, and accepted as the best available evidence of the position of the Original Corner. Place ¾"x5' pipe and cap marked "MEM 31600" inside.

ROSCOMMON COUNTY
PEER GROUP APPROVALDATE July 8, 1997

Marvin E. Myers MEM
Marvin E. Myers, P.S.
County Surveyor

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon. - 1½" pipe with ¾"x5' pipe and cap marked "MEM 31600" inside.
WIT: Set Carsonite post West 1.00'
Set ¾" x 5' pipe S51°E 10.00'
spike NW. side 3" Tamarack N34°E 42.55'
spike NW. side 3" Tamarack S63°W 68.65'
spike S. side 3" Tamarack S55°E 83.75'



Signed by Marvin E. Myers
Surveyor's Michigan License No. 31600

Date July 9, 1997

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 26, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

LIBER 3 PAGE 406