

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in  
ROSCOMMON  
(County)

Located In:

Corner Code ~~==~~

1. Public Land Survey

T 23M R 3M

M-5, M-6

T R

T R

T R

T R

2. Property Controlling  
in Section

S 13

T R

8, 11

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, CARL F. ROSER, in a field survey on JUNE 26, 19 91,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-5

M-6

8

(NO EVIDENCE OF G.L.O. CORNER, B.T.'S, LINE TREES & TOPOGRAPHY,  
AS CALLED OUT IN THE G.L.O. LINE NOTES; UNLESS NOTED IN ITEM "B"  
BELOW.)

NOTE: Above land corner's were recovered or set, and field corner records  
completed, during a survey in this area by D.N.R. Land Surveyor,  
Carl R. Johnson, L.S. #30083 (Now Retired). They are being recorded per  
Act 74, 1970, by Dept. Surveyor, C.F. Roser.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-5

M-6

8

11

FOUND AND ACCEPTED THIS  
SURVEY. SET BY UNKNOWN.

FOUND AND ACCEPTED THIS  
SURVEY. SET BY UNKNOWN.

SET BY STANDARD SURVEY  
PROCEDURE FOR SUBDIVISION OF A  
SECTION.

SET BY STANDARD SURVEY  
PROCEDURE FOR SUBDIVISION OF A  
SECTION.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-5

M-6

8

11

FD 1/2 BAR

FD IRON.

5/8" REROD W/CAP & CEDAR POST.

5/8" REROD W/CAP & CEDAR POST.

40" RED OAK S81°E 36.85'  
5" WH PINE N75°E 50.45'  
12" RED OAK N50°W 40.73'

8" RED OAK S38°E 60.6'  
6" RED OAK N61°E 62.3'  
5" RED PINE N62°W 49.3'  
12" RED PINE S86°W 64.9'

CEDAR 6" N20°E 27.5'  
CEDAR 5" S61°E 12.7'  
CEDAR 6" S28°W 4.0'  
CEDAR 8" N22°W 31.2'

BLACK ASH 4" N78°W 44.9'  
BLACK ASH 4" S84°W 35.3'

NAIL W/REF. TAGS.

NAIL W/REF. TAGS.

UPPER & LOWER BLAZES W/SCRIBES

DNR CUTTING TO NORTH & EAST.  
NAIL & BRASS TAGS. LOWER  
BLAZES.

Signed by Carl F. Roser 5-04-94 Date

Surveyor's Michigan License No. 12028