

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
RUSCONNON

(County)	Located In:	Corner Code #
1. Public Land Survey	T 23N R 3W	M-4, J-5
	T R	
	T R	
	T R	
2. Property Controlling in Section	S 36 T R	4, 5
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, CARL F. ROSER, in a field survey on NOVEMBER 6, 19 91,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:
M-4 J-5 4

(NO EVIDENCE OF G.L.O. CORNER, B.T'S, LINE TREES & TOPOGRAPHY,
AS CALLED OUT IN THE G.L.O. LINE NOTES; UNLESS NOTED IN ITEM "B"
BELOW.)

NOTE: Above land corner's were recovered or set, and field corner records
completed, during a survey in this area by D.N.R. Land Surveyor,
Carl R. Johnson, L.S. #30083 (Now Retired). They are being recorded per
Act 74, PA 1970, by Dept. Surveyor, C.F. Roser.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-4	J-5	4	5
FD AND ACCEPTED THIS SURVEY. SET BY UNKNOWN.	SET AT COMPUTED MEASUREMENT MIDWAY AND ON LINE BETWEEN SECTION CORNERS.	SET BY A CONTINUATION OF A PARTIAL SECTION SUBDIVISION SURVEY PERFORMED BY ARLETH SURVEY COMPANY.	SET BY A CONTINUATION OF A PARTIAL SECTION SUBDIVISION SURVEY PERFORMED BY ARLETH SURVEY COMPANY.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-4	J-5	4	5
FD 1/2" BAR.	DNR MON & CED POST.	5/8" REROD W/CAP & CEDAR POST.	5/8" REROD W/CAP & CEDAR POST.
6" WH PINE N41°E 87.74'	CEDAR 7" S03°W 6.45'	NO WITNESSES AVAILABLE.	MAPLE 6" N75°E 22.70'
14" RED PINE N84°W 36.05'	CEDAR 6" S72°W 14.55'	CORNER FALLS IN CRANBERRY BOG.	ASPEN 7" S59°W 21.60'
10" RED PINE S37°W 59.13'	MAPLE 10" N01°E 16.55'		ASPEN 5" N48°W 15.20'
MAPLE 6" S56°E 8.35'			
MAIL W/REF. TAGS.	UPPER & LOWER BLAZES W/SCRIPTS		BRASS TAGS & NAILS.

Signed by Carl F. Roser 5-04-94 Date _____

Surveyor's Michigan License No. 12028

