

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Roscommon (County)	Located In	Corner Code #
1. Public Land Survey	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
3. Miscellaneous Property in Section	S 4 T 24N R 01W 7	_____
	S 4 T 24N R 01W 14	_____

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Carl T. Kiiskila, in a field survey on January 11, 2011 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

7- N 1/16 corner common to sec.'s 3 & 4, T24N, R01W

None

14- S 1/16 corner common to sec.'s 3 & 4, T24N, R01W

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

7- N 1/16 corner common to sec.'s 3 & 4, T24N, R01W

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure. Corner falls in vertical railroad tie fence post with wire fence running South and West. Moved fence post 1' South and set monument. Corner is 29' West of centerline N-S gravel road. Found no other evidence to dispute the location for the corner.

14- S 1/16 corner common to sec.'s 3 & 4, T24N, R01W

Found 1/2" x 18" rebar with no cap 20' West of centerline N-S gravel road. Accepted found rebar as the best available evidence for the position of the original corner. Rebar fits well with galvanized post wire fence running East on East side of road. Replaced found rebar with stamped 2" dia. aluminum cap on 5/8" x 34" rebar. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

7- N 1/16 corner common to sec.'s 3 & 4, T24N, R01W

2" dia. stamped aluminum cap on 5/8"x34" rebar.

Wit: N52°E 76.37' to set N&T on SE side 3" Oak  
S64°E 74.46' to set N&T on SW side 6" Oak  
S74°W 11.86' to set N&T on N side 26" Oak  
N65°W 75.26' to set N&T on N side 10" W. Oak  
Set Blue Carsonite Post w/ loc. tag 1' North

14- S 1/16 corner common to sec.'s 3 & 4, T24N, R01W

2" dia. stamped aluminum cap on 5/8"x34" rebar.

Wit: N10°E 79.47' to set N&T on E side 9" B. Cherry  
N71°E 79.99' to set N&T on S side 24" S. Maple  
S31°E 13.54' to set N&T on SW side 8" B. Cherry  
N51°W 78.19' to set N&T on N side 5" B. Cherry  
N87°E 33.72' to West most galvanized post  
Set Blue Carsonite Post w/ loc. tag 1' North

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981

6-1-11

