

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Roscommon
(County)

Located In

Corner Code #

1. Public Land Survey T R
T R
2. Property Controlling in Section S 8 T 24N R 04W 6
S 8 T 24N R 04W 9
3. Miscellaneous Property in Section S
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on January 30, 2012 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

| | | | | | | | | | | | | | |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| | A | B | C | D | E | F | G | H | I | J | K | L | M |
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

6 - NE 1/16 Corner section 8, T24N,R4W

9 - CE 1/16 Corner section 8, T24N,R4W

None

1940's - Corner Index - Marcus Schaaf, P.S.#3104 - Index shows iron set. No witnesses.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

6 - NE 1/16 Corner section 8, T24N,R4W

9 - CE 1/16 Corner section 8, T24N,R4W

Set 2" dia. stamped aluminum cap on 5/8"x34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

Found 1 1/4" pipe badly rusted laying on the ground per M. Schaaf's index. Unable to determine the location of the base of the pipe set 2" dia. stamped aluminum cap on 5/8"x34" rebar per standard BLM procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

6 - NE 1/16 Corner section 8, T24N,R4W

9 - CE 1/16 Corner section 8, T24N,R4W

Stamped 2" dia. alum. cap on 5/8"x34" rebar

Stamped 2" dia. alum. cap on 5/8"x34" rebar

Witnesses:

S56°E 16.28' to set N&T on S side R.R Tie F. Post
S26°E 29.30' to set N&T on E side 6" Spruce
S58°W 45.12' to set N&T on S side 4" J. Pine
N10°W 31.34' to set N&T on E side 10" R. Pine Stump
Set Blue Carsonite Post w/loc. tag 1' North

Witnesses:

N10°E 7.47' to set N&T on NW side 5" Tamarack
S78°E 14.78' to set N&T on S side 5" Tamarack
S13°E 15.00' to set N&T on W side 6" Tamarack
N86°W 17.90' to set N&T on NE side 4" Tamarack
Set Blue Carsonite Post w/loc. tag 1' North

Signed by:

Carl T Kiiskila

Date:

6-28-12

Surveyor's Michigan License No.:

33981

