

APPROVED BY PEER GROUP  
P.A. 345 OF 1990

SAGINAW COUNTY

SAGINAW COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Saginaw

(County)

Located in:  
Thomas Twp.

Corner Code #

THOMAS TWP

1. Public Land Survey

T12N R 3E

T12N R 3E

T R

T R

T R

T R

T R

T R

E-5

E-6

2. Property Controlling  
in Section

S

S

S

S

3. Miscellaneous  
Property in Sec.4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Duane F. Ledy, in a field survey on October 25, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-5

Set post at 80.00 chains North of E-7; 1822, Joseph Wampler  
20" Sugar-S51 1/2°W, 8 links  
14" Sycamore-N35°W, 20 links

L.C.R.C. - Martin (L1, P110) 1971 R/R Spike

Survey - Martin (L1341, P586) 1971 R/R Spike

E-6

Set post at 40.00 chains North of E-7; 1822, Joseph Wampler  
18" Maple-S1°W, 38 links  
18" Birch-N35°W, 43 links

L.C.R.C. Martin (L1, P258) 1972 3/4" Pipe.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-5

Found Boat spike in Mon. box.  
L.C.R.C. and Survey witness:  
NE 38.53' (39.23' m) Fce T.P.  
NW 45.66' (45.51' m) Fce P. & T. P.  
SE 59.00' (59.85' m) Fce P. & T. P.  
SW 46.24' (46.34' m) Fce P. & T. P.

Monument accepted as best available evidence of original position.

E-6

Found 1" pipe in Mon box.  
L.C.R.C. witness:  
NE 103.62' (103.60' m) Fce P.P.  
SW 147.50' (147.5' m to brick) NE cor. Hse.

Monument accepted as best available evidence of original position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-5

Set 5/8" rod with remon. cap in monument box.  
NW 45.82' to PK nail in NE side P.P.  
NE 39.44' to PK nail in SE side P.P.  
SE 60.26' to PK nail in SW side P.P.  
SW 46.58' to PK nail in NW side P.P.

E-6

Set 5/8" rod with remon. cap over 1" pipe in monument box.  
NE 104.12' to nail in NW side P.P.  
SW 147.80' to NE corner house foundation  
S60°W 41.68' to nail in N side 6" Pine  
SE 204.47' to nail & tag in E side P.P.

Signed by

Duane F. Ledy

Surveyor's Michigan License No.

21575

Date

10/31/96



MAY 18 1997