

SURVEY &
REMONUMENTATION

SEP 17 1999

LIBER

2 PAGE 301

RECEIVED FOR RECORD

99 AUG -2 AM 9:09

SECTION

1999 REMONUMENTATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. 2 PAGE NO. 301
MICHELE VAINORMAN
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

For corners in

SANILAC

(County)

Located In:

Corner Code #

1. Public Land Survey

T11N R12E A-11

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, John A. Millettics, in a field survey on April 1, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1834 (Gov't. Land Office Notes) Harvey Parke, D.S.-set post Cor. Sections 25,36-Birch 11 S20W 19; Birch 10 N84W 8
1972 (Survey-Liber 1 of Surveys, page 349) David T. Rowe, P.S. 11192-End. 5/8" rod-N20°E 68.03' nail in N. side P.P.; S20°W 46.92' center cable box; N45°W 39.4' rd. sign post; N45°W 47.00' face on post chain link
1972 (Survey-Liber 2 of Surveys, pages 20 & 21) David T. Rowe, P.S. 11192-same marker and accessories as above Survey
1972 (Land Corner Recordation Certificate) David T. Rowe, P.S. 11192-Same marker and accessories as above Surveys

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A - 11

SW Corner Section 30 T11N-R12E

Found Standard Concrete Monument with Brass Cap

South 2657.60 feet to the W 1/4 Corner

North 2646.67 feet to the W 1/4 Corner

Accepted as best evidence

APPROVED PEER BOARD MEETING
July 20, 1999

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found Standard Concrete Monument W/2" Brass Cap
N50°E, 67.26' T.C. Remon. tag over found nail in NE face of power pole
S38°E, 38.82' set 5/8"x24" rerod
S45°W, 48.94' T.C. Remon. tag in NW Cor. 4x6 Tele. Pedestal Support
N40°W, 46.96' face of chain link fence corner post



Signed by John A. Millettics
Surveyor's Michigan License No. 25859

Date June 30, 1999