

REMONUMENTATION CORNER

LIBER **1** PAGE **412**
LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Sanilac Located In: Corner Code ##
 (County)

1. Public Land Survey T 11N R 13E I - 13
 T _____ R _____
 T _____ R _____
 T _____ R _____

2. Property Controlling S _____ T _____ R _____
 in Section S _____ T _____ R _____
 3. Miscellaneous S _____ T _____ R _____
 Property in Sec. S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____
 5. Private Claims _____

RECEIVED FOR RECORD

93 DEC 17 PM 1:56

LIBER NO. 1 PAGE NO. 412
 ESTHER LEE
 REGISTER OF DEEDS
 SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

I, John A Milletics, in a field survey on Aug 23, 1993,
 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
 current manual of survey instructions of the United States Department of the Interior, Bureau of Land
 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
 Court of Law; established, re-established, monumented, re-monumented, recovered, found as
 expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
 on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

I - 13 Found P.K. nail in blacktop, per survey recorded in Liber 4, Page 581 of the
 Sanilac County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I - 13
 SE Cor Section 34 T11N-R13E
 Found P.K. nail

SURVEY &
 REMONUMENTATION

1993

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I - 13
 SE Cor Section 34 T11N-R13E
 Set Monu Box
 South 18.62' to the west leg of a Road Sign
 S80°W 76.65' to the Easr leg of a Road Sign
 N75°E 64.70' to a Tele Box
 N10°W 53.00' to the West end of a 15" CMP

Signed by John A Milletics Date Dec. 15, 1993Surveyor's Michigan License No. 25859