

JAN 22 2001

LIBER

3 PAGE 35

SECTION

2000 Remonumentation Program  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD

00 NOV 27 AM 8:55

LIBER NO. 3 PAGE NO. 35  
MICHELE VANKORMAN  
REGISTER OF DEEDS  
SANILAC CO. MICHIGAN

For corners in

Sanilac

(County)

Located In:

Corner Code #

1. Public Land Survey

T11N R15E

I - 1

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

Lot No. , Recorded Plat  
Private Claims

2000

John A Milletics, in a field survey on May 1, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in accordance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or at the corner points mentioned in lines 3, 4 and 5 above were in accordance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, covered, found as expressed below:

DTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Description of original monument and accessories and/or subsequent restoration:

GLO Notes

Beech 12" S31°W 8 Links

Beech 12" S43°E 31 Links

Old Survey Liber - None

Act 132 - Liber 4 Page 95 Sanilac Land Survey March 1978

Liber 3 Page 764 Kay Eng Aug 1977

Unrecorded Surveys - Milletics Oct 1997

Sanilac Land Survey Aug 1979

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I - 1

NE Corner Section 3 T11N-R15E

Found 5/8" Iron Bar in Monu Box

West 2627.64 Feet to the N 1/4 Corner Section 3

East 2676.92 feet to the N 1/4 Corner Section 2

Accepted as best evidence

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I - 1

NE Corner Section 3 T11N-R15E

5/8" Iron in Monu Box

West 35.40 feet to the SW Corner Section 35

S45°E 49.72 feet to the NW Corner of a Building

S35°E 47.52 feet to a nail in a Power Pole

N45°W 48.95 feet to a nail in a Power Pole

S85°W 47.80 feet to the center of a Manhole cover

West 2627.64 feet to the N 1/4 Corner Section 3

East 2676.92 feet to the N 1/4 Corner Section 2

APPROVED PEER BOARD  
MEETING NOV 25 2000

ed by John A Milletics

Date Nov 15, 2000

Surveyor's Michigan License No. 25859