

# SURVEY & REMONUMENTATION

SEP 17 1999

LIBER

2 PAGE 308

RECEIVED FOR RECORD

99 AUG -2 AM 9:09

SECTION

1999 REMONUMENTATION PROGRAM  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. 2 PAGE NO. 308  
MICHELE VANNORMAN  
REGISTER OF DEEDS  
SANILAC CO. MICHIGAN

For corners in

SANILAC  
(County)

Located In:

Corner Code #

1. Public Land Survey

T12N R12E

A-6

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, John A. Millettics, in a field survey on April 1, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1834 (Gov't. Land Office Notes) Harvey Parke, D.S.-Set qr. Sec. post-B. Ash 12 N18W 41; Elm 8 S7W 23

Tuscola County L.C.R.C. Form Liber \_\_\_\_\_ Page \_\_\_\_\_ Filing No. 50

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A - 6

W 1/4 Corner Section 18 T12N-R12E

Found Stand Concrete Mounment with Brass Cap

South 2619.86 feet to the SW Corner Section 18

North 2618.86 feet to the NW Corner Section 18

Accpeted as best evidence

APPROVED PEER BOARD MEETING  
July 20, 1999

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found Standard Monument with 2" Brass Cap

N12°E, 29.67' T.C. Re-mon. tag in East face of 6" Elm

S30°E, 36.31' T.C. Re-mon. tag in Northeast face of 8" Poplar

West, 39.02' T.C. Re-mon. tag in North face of 12" Willow

N85°E, 34.73' T.C. Re-mon. tag in Southeast face of 14" Elm

South, 1.0' "Survey Marker" witness post

Signed by John A. Millettics  
Surveyor's Michigan License No. 25859

Date June 30, 1999

