

APR 14 1998

SECTION REMONUMENTATION

LIBER

2 PAGE 183

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in CUSTER TOWNSHIP

Sanilac (County)	Located In:	Corner Code #
1. Public Land Survey	T12N R14E	E - 8
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

RECEIVED FOR RECORD

97 DEC -2 AM 9:11

LIBER NO. 2 PAGE NO. 183

ESTHER LEE REGISTER OF DEEDS SANILAC CO., MICHIGAN

SURVEY & REMONUMENTATION

JAN 08 1998

SECTION

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, John A Milletics, in a field survey on July 15, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	10		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:  
E - 8

GLO Notes

- Set 1/4 Section Corner
- B. Ash 9 N12°E 9
- B. Ash 10 N54°W 9

Old Survey Liber, Survey dated May 1902 by Nicol  
Act 74 None  
Act 132 None  
Unrecorded surveys dated 5-12-71, 4-6-84 12-16-94 showing section break down

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

E - 8

Found Moun Box in place with 5/8" iron bar

APPROVED PEER BOARD MEETING  
NOV. 26, 1997

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E - 8

- E 1/4 Corner Section 20 T12N-R14E Custer Twp.
- Monu Box in place with 5/8" Iron Bar
- East 21.55 feet to a 1/2" Iron Bar
- West 53.42 feet to a nail in a Power Pole
- S85°W 51.68 feet to a Telephone Riser Box
- S45°W 35.80 feet to a Road Sign
- North 2673.49 feet to the NE Corner Section 20
- South 2672.80 feet to the SE Corner Section 20



Signed by John A. Milletics  
Surveyor's Michigan License No. 25859

Date Nov 12, 1997