SURVEY & REMONUMENTATION

APR 1 4 1998

LBER

2 PAGE 185

RECEIVED FOR RECORD

REMONUMEN		
SEU	Uľ	di .

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

97 DEC -2 AM 9: 11

105

For corners in CUSTER	TOWNSHIP		ESTHER I FE
Sanilac (County)	Located In:	Corner Code #	ESTHER LEE REGISTER OF DEEDS SANILAC CO. MICHIGAN
1. Public Land Survey	T <u>12N</u> R T R T R T R		SURVEY & REMONUMENTATION
Property Controlling in Section Miscellaneous	S TR S TR S TR		JAN 0 8 1998
Property in Sec.	S TR		SECTION Register of Deeds Stamp & File Number
4. Lot No, Reco	orded Plat		A B C D E F G H I J K L

I, John A Milletics , in a field survey on $\underline{July\ 14}$, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the July 14, 1997 do hereby state that under United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

	A	B	С	D	E	F	G	H	1	J	К	LA
1		1	Τ		Т	T	T		1		T	
2	-	6—		-5-	+	4-	+	- ၌	-	2	+	1-
3		╁	+-		+	╀	-	+	1	-	╀	┡
4	┝	 1	╁	- 8 -	┼-	9	+	-10	-:	¦1—	+	1,2—
5	-	-	+		┼	╁	╁	╅-	╁	H	╂	├-
6	<u> </u> j	ļ 9 —	┼-	-17	┼:	16	- -	-15	 	4—		13
7		-	╀	+-	╁—	╁	+	┿	-	ļ	╄	-
8	1	<u> </u> 9_	+	-20		/ ₁ _	\perp	-2 2	 :	! 3	 2	4—
9		L	-	-	\bot		<u> </u>		<u> </u>	L	ļ	<u> </u>
10	:	! 30—	╀-	29-	.	! 2 <mark>8</mark> —	1	-2 <u>,</u> 7	2	! :6	<u> </u>	l 25—
11	_	<u> </u> -	-	1	╀-	├-	_		_	L	<u> </u>	<u> </u>
12	<u> </u>	! !1—	<u> </u>	.32 <u>—</u>	\perp	 33—	\perp	-34	<u>L</u> 3	 5	<u>Ļ</u> ;	 36
13			<u> </u>]				<u> </u>	<u> </u>		

A. Description of original monument and accessories and/or subsequent restoration:

GLO Notes

Set 1/4 Section Post.

Hemlock 10 N87°E 10

Hemlock 15 S69°W 19

Old Survey Liber, Survey dated April 1894 by Galbraith, and survey dated Aug 1906 by Nicol

Act 74 None

Act 132 Liber 3 Page 621

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

Found Moun Box in place with iron

APPROVED PEER BOARD MEETING NOV. 26, 1997

 Description of monument for corner and accessories established to perpetu 	rate locating the position of the corner.
E - 10	Willia of Mickelly
E 1/4 Corner Section 29 T12N-R14E Custer Twp.	
Monu Box in place with iron and cap	N. O. W. Mer. L.
East 49.46 feet to a 1/2" Iron Bar	
S80°W 63.45 feet to the NE Cor of a Building	John A. Milletics 12
N70°W 46.50 feet to a nail in a 30" Poplar	→ • Land Surveyor • ~ = =
N40°W 79.96 feet to a nail in a 24" Maple	No. 25859
South 2664.22 feet to the SE Cor Section 29	
North 2664.00 feet to the NE Cor Section 29	The same of the sa
Note in 2004.00 feet to the NE Cor Section 29	My one Sulling
- lansell	
Signed by ANI MUST	DateNov 12, 1997
Surveyor's Michigan License No. 25859	
· · · · · · · · · · · · · · · · · · ·	•