

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

98 DEC -1 AM 9:08

LIBER NO. 2 PAGE NO. 239

For corners in

Sanilac

(County)

Located in:

Corner Code #

1. Public Land Survey

T13N R13E

A-7

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

MICHELE VAN NORMAN
REGISTER OF DEEDS
SANILAC CO., MICHIGAN

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, John A. Milletics, in a field survey on Oct 5, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-7 GLO Notes - Maple 10 N31W 52; Butternut 12 S5 1/2W 52

Old Survey Liber-Survey by Thomas Nicol 1905

Survey by Thomas Nicol 1906

Act 132 - None

L.C.R.C.- None

Unrecorded survey dated 10-14-86

SURVEY &
REMONUMENTATION

JAN 15 1999

SECTION

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-7 SW Corner Section 18 T13N-R13E

Found 1/2" iron bar in gravel road bed

Accepted as best evidence

North 2653.00 feet to the W 1/4 Corner Section 18

South 2647.20 feet to the W 1/4 Corner Section 19

APPROVED PEER BOARD MEETING
NOV 30, 1998

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-7

1/2" Iron Bar with cap

East, 19.20' To North Leg Road Sign

East, 28.20' To Nail in Fence Post

S30°E, 55.60' To Nail in 8" Ash

S45°W, 68.75' To Nail in 48" Oak

North 2653.00 feet to the W 1/4 Corner Section 18

South 2647.20 feet to the W 1/4 Corner Section 19

Signed by

John A. Milletics

Date

Nov 18, 1998

Surveyor's Michigan License No. 25859

