

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

96 DEC 10 AM 11:55

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER NO. 2 PAGE NO. 91
ESTHER LEE
REGISTER OF DEEDS
SANILAC CO. MICHIGANFor corners in
Sanilac

(County)

Located In:

Corner Code #

1. Public Land Survey

T 13N R 14E

H-13, I-13

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, JOHN A MILLETICS, in a field survey on June 1, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H - 13 GLO NOTES

40.00 Set 1/4 Section Post

Elm 9 N58E 7

Elm 10 N30W 10

NO Survey in Old Liber

Unrecorded Survey dated 3-94 S 1/2 of Section Run

Act 74 None, Act 132 None

No Road or Drain Comm. Records

I - 13 GLO NOTES

80.00 Set Post Corner

Tamarack 10 N72E 43

Tamarack 8 N56W 13

No Survey in Old Liber

Unrecorded Survey dated 3-94 S 1/2 of Section Run

Act 74 None, Act 132 None

No Road or Drain Comm Records

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H - 13

S 1/4 Cor Section 34 T13N-R14E

Found 1/2" Iron Bar in Gravel Road Bed

half way between SE and SW Section Corners

I - 13

SE Corner Section 34 T13N-R14E

Found 1/2" Iron Bar

APPROVED PEER BOARD MEETING

12-02-96 97

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H - 13

S 1/4 Corner Section 34 T13N-R14E

1/2" Iron Bar in Gravel Road Bed

S30°E 38.57 to a 1/2" iron Bar

S20°E 51.21 to a nail in a 12" Maple

S20°W 66.25 to a nail in a 10" Apple

East 16.83 to a 1/2" Iron Bar N 1/4 Cor
Section 3

West 2653.18 feet to the SW Cor Section 34

I - 13

SE Cor Section 34 T13N-R14E

1/2" Iron Bar in Gravel Road Bed

N60°E 58.73 to a nail in a power pole

S45°W 47.82 to a Bell Box

East 33.66 to a 1/2" Iron Bar in gravel Road Bed

NE Corner Section 3

West 2653.18 to the S1/4 Section 3

Signed by

Date

Aug 4, 1996

Surveyor's Michigan License No.

25859