

ST. CLAIR COUNTY, MICHIGAN
OFFICIAL GOVERNMENT CORNER



LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Located In: Corner Code #

1. Public Land Survey T 7N R 15E B-13
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

Sec. 1

RECEIVED
1993 DEC 29 AM 9:44
REGISTERED
ST. CLAIR COUNTY
Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, David J. Little, in a field survey on Sept. 27-30, 1993,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 1 corner, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
Post-(Government Surveys)

Nothing listed on Old Surveyor's Record
St. Clair County.

Recordation Certificate shows Corner being recorded in E. _____
L.4 P.132. This Certificated has incorrect Corner code
number. This Certificate was recorded as the N $\frac{1}{4}$ Sec. 6. ELEVATION _____

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
Set "T" Iron stamped LLS 31596.

Set "T" Iron on line with the NW Corner Section 6, T6N, R15E, and the SE Corner
Section 31, T7N, R15E and on line with an existing old fence running North
to Lapeer Road.

Partial remains of old fence going North.

2159A000 12/29/93MSSU# 9.00
0001
2159A000 12/29/93SSRF# 2.00
0001

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

"T" Iron stamped LLS 31596.

ENE 36.35' to set P.K. and County Tag in S face of 40" Maple.
SE 75.15' to set P.K. and County Tag in W face of 36" Maple.
SE 71.55' to set P.K. and County Tag in W face 36" Maple.

See attached sketch for additional information.

Signed by David J. Little
Surveyor's Michigan License No. 31596

Date December 18, 1993

APPROVED AS AN OFFICIAL GOVERNMENT CORNER BY ST. CLAIR COUNTY:

Signed By: _____ Date _____
St. Clair County Land Surveyor

Surveyor's Michigan License No. _____

PA 345-1990
PEER COMMITTEE
APPROVED 12-14-93

LIBER 007 PAGE 185

DAVID J. LITTLE
2833 GRATIOT BOULEVARD, MARYSVILLE, MICHIGAN 49040
LICENSED LAND SURVEYORS

0. J. C.
12.10.93

93.127

Certificate of Survey

