NOV 0 4 1997

Surveyor's Michigan License No. 14100

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

PAGE 340

For corners in	LIBER T PAGE OTV
ST. JOSEPH Located in: Corner Code #	STATE OF MICHIGAN ST. JOSEPH COUNTY
LEONIDAS TWP. 1. Public Land Survey T_55 R_9W C-1	FILED
TR	20 MAY 97 11:55 A.M.
T R 2. Property Controlling S T R in Section S T R	CYNTHIA JARRATT REGISTER OF DEEDS
3. Miscellaneous S T R	
1	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
5. Private Claims	1 B B D E F G H I J K L
	2 6 5 4 3 2 1 1
I, Wayne A. Mostrom, in a field survey on May 8, 1997 do hereby state that under	er 4 7 8 9 10 11 12
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the	in 5
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and k that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michiga	or 6 - 10 17 16 15 14 12
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented recovered, found as expressed below:	d, /
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	8 -19 - 20 - 21 - 22 - 23 - 24 - 9
on this certificate.	10 30 29 28 27 26 25
•	11
	12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	13
GLO 1865 SURVEY IN A/116	1926 ROAD SURVEY BY MCCOY
8" BEECH = $$62^{\circ}E$ 9 LKS. 20" W. WOOD = WEST 10 LKS. STAKE FROM INTER. OF LINES 10" SYCAMORE = $$N73^{\circ}E$ $45\frac{1}{2}$ LKS. 6" BL. WALNUT = $$40^{\circ}W$	SURVEY SHOWS STONE 6.61
O BE. WALNOT 2 340 W	•
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.	orner:
DUG WITH COUNTY ROAD COMMISSION BACKHOE AND FOUND.	
SQUARE TOP STONE WITH "+" ON TOP 9.8" W. OF C	
IRON BAR FOUND IS 1.76' E. OF STONE - NOTHING UNDER BAR FOUND SECOND IRON BAR 38.2' EAST OF FIRST IRON	
BUT NOTHING WAS FOUND UNDER IT AFTER DIGGING 6' X 6' HOLE 41'	DEEP.
***	FIED BY PEER GROUP
IN AC ON	CCORDANCE WITH P.A. 345 MAY (2 , 19 <i>9</i> 7
	CO. REPRESENTATIVE
C. Description of monument for corner and accessories established to perpetuate locating the p	
SET 5/8" X 24" BAR WITH STD. CAP IN MON. BOX (OLD STONE WAS LAID SIDEWAYS OUTSIDE BOX) NE: COR. "A.C. MINNIS" HEADSTONE = \$81°W 27.74"	ATE OF MICHICAN
SE COR. "BEARD" HEADSTONE = N45°W 41.22' SE COR. RR TIE A.P. = N58°E 74.73'	WAYNE A. MOSTROM PROFESSIONAL
N & W IN NE SIDE 28" WALNUT = \$69°E 99.30"	PROFESSIONAL 5 SURVEYOR 5
© RDWY = EAST 9.8' IRON FOUND = EAST 1.76'	No.
	S A S S S S S S S S S S S S S S S S S S
11)a. (11. #	14100 PARTIES SIONAL PROPERTY OF THE PROPERTY
Signed by William S. White Date	5/17/97