

MAY 07 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
St. Joseph
(County)

Located In:

Corner Code #

LIBER 4 PAGE 286

STATE OF MICHIGAN
ST. JOSEPH COUNTY
FILED

30 DEC 96 1:59 P.M.

CYNTHIA JARRATT
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey T 5S R 10W F-9
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

I, Donald C. Andrews, in a field survey on October 10, 1996, do hereby certify that under requirements of P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F-9
GLO Post

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2								
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-9
Found Stone at NW Corner 28 (E-9) approved by Remon. peer group and at the W1/8th Corner Section 28 found "X" stone in monument box. Doubled over distance using the monumented line for (F-9). The westerly 1/2 mile is 1.25 feet less then the split of the distance between (E-9) and (G-9). Also it is close to being on line between the two corners (E-9) and (G-9). Dub a 4'x4' hole about 2.5' deep. Nothing found.

RATIFIED BY PEER GROUP
IN ACCORDANCE WITH P.A. 345
ON May 13, 1996
W. C. Andrews CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-9
Set Alum. capped 5/8"x24" long iron in monument box: 1) 16" oak N35°W 30.68', 2) 24" twin Hickory S50°E 35.41', 3) 14" Hickory N50°E 69.32', 4) PP N50°W 54.73'

Signed by Donald C. Andrews
Donald C. Andrews, P.S.

Surveyor's Michigan License No. 33967



Date 12/23/96

REMONUMENTATION