

# SURVEY & MONUMENTATION

JAN 17 1996

## COMMISSION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ST. JOSEPH  
(County)

Located In:

Corner Code #

PARK TWP.

1. Public Land Survey

T 5S R 11W

E-2

2. Property Controlling  
in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

LIBER 4 PAGE 146

STATE OF MICHIGAN  
ST. JOSEPH COUNTY  
FILED

11 MAY 95 4:30 P.M.

CYNTHIA JARRATT  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, DAVID W. MOSTROM, in a field survey on MARCH 24, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:  
(E-2) 1/4 CORNER COMMON TO SECTIONS 4 & 5

1974 SURVEY BY MOSTROM &  
LCRC IN BOOK 2, PG. 32 & BOOK 3, PG. 20

SET 18" IRON BAR USING SURROUNDING  
CORNERS IN SECTIONS 4, 5, 8 & 9  
8" PIN CHERRY = N60°E 40.9'  
10" HICKORY = N69°E 57.15'  
30" ELM STUMP = S31°E 22'  
30" OAK = S70°E 73.38'

1976 SURVEYS BY SNELL &  
LCRC IN BOOK 2, PG. 76  
FOUND IRON BAR & CAP  
8" CHERRY = N60°E 48.9'  
IN CENTERLINE OF EXIST. ROAD  
N. END CULVERT = N8°E 32'  
S. END CULVERT = S16°E 17'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E-2)

FOUND CAPPED IRON #14100 IN MON. BOX IN CENTERLINE OF EXISTING GRAVEL ROAD  
AND OVER OPEN DITCH RUNNING NORTH-SOUTH

12" CHERRY = N62°E 49.20'  
10" HICKORY = N69°E 57.15'  
30" ELM STUMP = S31°E 22'  
30" OAK = S70°E 73.38'  
N. END CULVERT = N08°E 32.10'  
S. END CULVERT = S16°E 17.45'  
CORNER FALLS S20°47'E 1.87'  
FROM PROPORTIONED DISTANCE  
BETWEEN NE COR. & SE. COR. SEC. 15

RATIFIED BY PEER GROUP  
IN ACCORDANCE WITH P.A. 345  
ON MAY 8, 1995  
CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
(E-Z) 1/4 CORNER COMMON TO SECTIONS 4 & 5

SET 5/8" X 24" IRON BAR W/STD. CAP IN MON. BOX IN PLACE OF CAPPED IRON FOUND  
CORNER FALLS IN CENTERLINE OF MUSKRAT ROAD OVER OPEN DITCH THAT RUNS N-S  
NORTH END OF CULVERT = N08°E 32.10'  
SOUTH END OF CULVERT = S16°E 17.45'  
N & W 2' HIGH ON SE. SIDE OF 12" CHERRY = N62°E 49.20'  
N & W 2' HIGH ON E. SIDE OF 36" OAK = S70°E 73.38'

Signed by

*[Signature]*

Date

MAY 9, 1995

Surveyor's Michigan License No.

32339

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1987

# REMONUMENTATION

