

004 PG 045

# LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FILED

JUN 27 12 47 PM '94

*Cynthia R. J. J. J.*  
REGISTER OF DEEDS  
ST. JOSEPH CO. MICH.

For corners in

ST. JOSEPH  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 5S R 11W

G-4

T R

T R

T R

2. Property Controlling  
In Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

**SURVEY &  
REMONUMENTATION**

AUG 31 1994

Register of Deeds Stamp &amp; File Number

4. Lot No. , Recorded Plat

COMMISSION

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, WAYNE A. MOSTROM in a field survey on NOV. 8, 1993, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

G-4

1966 SURVEY BY INGERSOLL

7" W.O. = N73°E 22LKS

FD. CAPPED IRON IN MON. BOX

6" B.O. = S5°W 35LKS

L.C.R.C. (3/21) &amp; 1974 SURVEY BY W. MOSTROM

PIPE IN MON. BOX IN CL ASPHALT RD.

ROAD SIGN = N77°E 20.8'

8" PEAR TREE = S42°E 36.3'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-4

8" PEAR TREE = S42°E 36.3'

FD. PIPE OVER STONE IN MON. BOX

RATIFIED BY PEER GROUP  
IN ACCORDANCE WITH P.A. 345  
ON Nov. 8<sup>th</sup>, 1993  
Wayne CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-4 (1/4 COR. COMMON TO SEC'S 9 &amp; 10)

SET 5/8" X 10" BAR W/STD. CAP OVER STONE  
IN MONUMENT BOX

N &amp; W IN W. SIDE 16" DBL. WALNUT = N9°E 184.65'

N &amp; W IN N. SIDE 26" CHERRY = S88°W 207.67'

COR IS IN CL RDWY TO W. &amp; N.

N. &amp; W. EDGES/HOUSE ( TO SE) PROJ. ARE 83.8'S &amp; 80.55'E



Signed by

*Wayne A. Mostrom*

Date

5.24.94

Surveyor's Michigan License No.

14100

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

**REMONUMENTATION**