

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 4 PAGE 227

For corners in ST. JOSEPH Located in: _____ Corner Code # _____
 (County)

1. Public Land Survey T 5S R 11W K-2
 T _____ R _____
 T _____ R _____
 T _____ R _____
2. Property Controlling S _____ T _____ R _____
 in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
 Property in Sec. S _____ T _____ R _____
4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

STATE OF MICHIGAN
 ST. JOSEPH COUNTY
 FILED

18 JUN 96 9:14 A.M.

CYNTHIA JARRATT
 REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Donald C. Andrews, in a field survey on MAY 30, 1996, do hereby certify that under requirements of P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO POST
 1875 BK A, P 210 STAKE
 1916 BK B, P 506 POST (STAKE)
 1965 CO. ROAD RECORDS - PIECE OF METAL
 1981 MOSTROM FOUND 1-1/2" WIDE METAL BAR WITH 9"X7" PLATE OVER IT. 14" CHERRY N36°E 22.33', 14" OAK S68°E 44.10'
 1995 MOSTROM FOUND 1-1/2" WIDE METAL BAR. MAPLE CLUSTER N29°W 24.0', 16" CHERRY N36°E 22.33', 16" DBL. OAK S68°E 44.10'

**SURVEY &
 RE-MONUMENTATION**

OCT 03 1996

COMMISSION

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND NOTCHED 1-1/4" X 1/4" METAL BAR DRIVEN THROUGH REMAINS OF STAKE. RESET BAR WITH 5/8"X24" IRON THROUGH REMAINS OF STAKE.

RATIFIED BY PEER GROUP
 IN ACCORDANCE WITH P.A. 345
 ON MAY 13, 1996
Don CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8"X24" IRON WITH STANDARD ALUM. CAP:
 18" OAK S35°E 73.75'
 10" QUINT MAPLE N40°W 24.00'
 18" TRIP. CHERRY N30°E 22.27'
 24" TWIN MAPLE S70°E 44.06'



Signed by Donald C. Andrews
 Donald C. Andrews, P.S.
 Surveyor's Michigan License No. 33967

Date 5/31/96

LIBER 4 PAGE 227