

NOV 0 4 1997

EX-100-155-15

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ST. JOSEPH

Located In:

Corner Code #

(County)

COLON TWP.

1. Public Land Survey

T 6S R 9W

B-3

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

3. Miscellaneous

S

T R

Property in Sec.

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

I, DAVID W. MOSTROM, in a field survey on AUG. 9, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below.

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B-3) 1/4 CORNER COMMON TO SECTIONS 6 & 7 T6S, R9W

*1866 SURVEY IN BOOK A, PG. 144
STAKE MIDWAY BETWEEN SECTION
CORNERS AFTER ALLOWANCE FOR
FRACTION
30" Y. OAK = N70°E 1.10½ CH.

*1961 ROAD COMMISSION
1/2" PIPE OVER STONE
IN MON. BOX
28" CLUMP ELM =
N40°W 59.05'
17" PIN OAK = N65°E 78.28'
39" OAK = SOUTH 80.01'

*1989 LCRC IN BOOK 2, PG. 270
FOUND 3/4" PIPE IN MON. BOX
24" OAK = N70°E 78.24'
6" OAK = N50°E 58.41'
20" TRIPLE OAK = N50°W 78.53'
FENCE POST = S05°W 33.45'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(B-3)

FOUND 3/4" X 25" PIPE OVER POINTED STONE 36" DEEP IN MONUMENT BOX

28" OAK = N70°E 78.24'

48" OAK = S02°W 80.01'

14" OAK = N50°E 58.41'

24" TRIPLE OAK = N50°W 78.53'

FENCE POST = S05°W 33.54'

CORNER FALLS IN CENTERLINE OF ORLA ENGLE
ROAD (GRAVEL) AND 1.5' E OF FENCELINE
PROJECTED TO SOUTH.

THIS IS A 3-4' FILL AREA.

RATIFIED BY PEER GROUP
IN ACCORDANCE WITH P.A. 345
ON SEPT. 8, 1997
CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B-3) 1/4 CORNER COMMON TO SECTIONS 6 & 7 T6S, R9W

SET 5/8" X 24" IRON BAR W/STD CAP OVER STONE IN MONUMENT BOX
DBL. HEAD NAIL & WASHER IN TOP OF FENCEPOST = S05°W 33.54'

N & W 4' HIGH IN E. SIDE OF 48" W. OAK = S02°W 80.01'

N & W 3' HIGH IN SW SIDE OF 10" OAK = N45°W 69.23'

N & W 3' HIGH IN SE SIDE OF 14" OAK = N60°E 58.41'

N & W 3' HIGH IN NE SIDE OF 10" WALNUT = S32°E 34.59'

Signed by DAVID W. MOSTROM

Surveyor's Michigan License No. 32339

Date SEPTEMBER 9, 1997

LIBER 5 PAGE 19

STATE OF MICHIGAN
ST. JOSEPH COUNTY
FILED

17 SEP 97 3:26 P.M.

CYNTHIA JARRATT
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													



LIBER 5 PAGE 19