LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 LIBER 6 PAGE 48 STATE OF MICHIGAN ST. JOSEPH COUNTY

FILED

Corner Code #

For corners in Nottawa Twp.

St. Joseph County

Located In:

1. Public Land Survey T §	3 S R 10 W I-13	f tren
T_	R	20 JUN 2000 11:18:38 AM
T_ T_ 2. Property Controlling S T_	R SURVEY & REMONUMENTATION	CYNTHIA L. JARRATT
in Section S T_	<u>R</u>	REGISTER OF DEEDS
3. Miscellaneous S T_ Property in Sec. S T_	R JA <u>N 31 2001</u>	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	SECTION	_ 2 6 5 4 3 2
		3 4 7 8 9 10 11 12
I. Wavne A. Mostrom, in a field survey on May 2, 2000 of	o state that under requirements of P.A. 74, Michigan P.A. of 1	970, 5
the corner points mentioned in lines 1 and 2 above were in	conformance with regulations and rules therefore as required Department of the Interior, Bureau of Land Management or	in the 6 10 17 16 15 14 13
degree of a Court of Law and/or that the corner points men	tioned in lines 3, 4 and 5 above were in conformance with the ree of a Court of Law, established, re-established, monume	rules 7
recovered, found as expressed below:	ice of a court of Larr, commented, to commented, the many	
NOTE: Not more than 2 comers, all in the sam	e town and range, may be recorded on this certific	ate. 10 30 29 28 27 26 25
		11
		12 31 32 33 34 35 36
		13
A. Description of original monument and a	ccessories and/or subsequent restoration:	
<u>GLO</u> 7" Burr Oak = N41°E 108 Lks (71.28')	Road Commission Dug for corner - nothing found.	Sayers 1973 Survey Pipe in Mon. box
8" W.O. = N28°W 82 Lks (54.12')	Found +'d stone 1/4 mile East (Nott. Cor.)	39.67' East of NE cor. Sec. 3
1863 Survey in A/38	and pipe thru decayed stake at NW Cor. Sec. 2. Set 1/2" pipe 39.6'	Mostrom 1993 Survey
Stone 14" W.O. = N22°E 45 iks (29.70')	to East per GLO jog and on line with corners found	Found 3/4" pipe in Mon. box 39.66' E. of NE Cor. Sec. 3
14 VV.O 1422 E 40 IR3 (20.70)		as recorded in L-1, P-53
B. Description of corner evidence found an	d/or method applied in restoring or reestablis	hing corner:
Found 3/4" pipe in Mon. box 1' South of		•
with CL Nottawa Road to the North.	•	RATIFIED BY PEER GROUP
Pipe in Mon. box @ Sherman Twp. corn	er is 39.66° West.	IN ACCORDANCE WITH P.A. 345
		ON JUNE 12 , 2000
		CO. REPRESENTATIVE
C. Description of monument for corner and	d accessories established to perpetuate locat	ing the position of the corner:
Replaced pipe found with 5/8" x 24" with N & W in N. side 30" Wal. = \$66°E 59.4		OF MICH.
N & W in S. side P.P. = N49°E 39.26'		MATE OF MICH OF
N & W in SE side P.P. = S68°W 76.20' N & W in W. side 24" Hick. = N26°E 62	.13'	WAYNE A. WOSTROM
		PROFESSIONAL DE SURVEYOR
	_	PROFESSIONAL SURVEYOR NO. 14100 PAGE
\sim		MOSTROM * MOSTROM * PROFESSIONAL SURVEYOR No. 14100 APOFESSIONAL * PAGE ** ** ** ** ** ** ** ** ** ** ** ** **
11 /)/		TO FESSION WHITE
11/84	0.5	
Signed by	wy>	Date June 15, 2000
Surveyor's Michigan Litense No. 14100		
FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 18, 1971 REVISED MAY 14, 1975		
REVISED JAN., 1983 REVISED OCT., 1995		

REMONUMENTATION