## Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 6 PAGE 53 STATE OF MICHIGAN

26 JUL 2000 10:29:08 AH

ST. JOSEPH COUNTY FILED

CYNTHIA L. JARRATT REGISTER OF DEEDS

Register of Deeds Stamp & File Number

St. Joseph County (County)	Located In:	Corner Code #
Public Land Survey	- - -	T_6S_R_12WG-11 TR TRT_RT_RT_RT_RT_RT_RT_RT_RT_RT_RT_RT_R
2. Property Controlling in Section	s :	T R REMONUMENTATION
3. Miscellaneous Property in Sec.	s	TR JAN 31 2001
	orded Plat _	SECTION
in Section 3. Miscellaneous Property in Sec.	s : s :	TR

, 20\_00\_do state that under requirements of P.A. 74, Michigan David W. Mostrom in a field survey on June 21, P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a degree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, reestablished, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

CORNER COMMON TO SECTIONS 27, 28, 33 & 34, FABIUS TOWNSHIP

A. Description of original monument and accessories and/or subsequent restoration:

14" W. ASH = S28°W 17.16' 9" BEECH = N59°E 15.84'

For corners in Fabius Township

1865 SURVEY IN BOOK A, PAGE 132 STAKE SET FROM OLD BEARINGS 10" BEECH = NORTHWEST 20.79'

1886 SURVEY IN BOOK A, PAGE 542 STONE SET FROM ORIGINAL BRG'S BY A FORMER SURVEYOR 6" ELM = S13 1/2"E 26.4" 6" ELM = \$26°E 26.4"

1947 MDOT

CHISELED + 2.09' NORTH OF **EXISTING CENTERLINE** 19" WALNUT = N57°E 36.01' 29" ELM = \$65°E 53.00" 22" ELM = \$60°E 23.98'

1961 SAYERS SURVEY
CORNER USED BUT NOT LABELED OR WITNESSED

LAND CORNER RECORDATION CERTIFICATE

1971 PLAT OF FABIUS FARMS ESTATES CONC. MONUMENT = NORTH 33.00'

> 1975 LCRC IN BOOK 2, PAGE 15 P.K. NAIL IRON POST = SOUTH 33.75' CONC. MONUMENT = NORTH 33' 20" TREE = \$45°E 35 88"

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND P.K. NAIL IN OLD HIGHWAY DUG 2' X 2' X 48" DEEP HOLE UNDER NAIL BUT FOUND NO EVIDENCE OF STONE 24" WALNUT = N57°E 36.01' CONC. MONUMENT (BENT) = NORTH 33.00 IRON POST = SOUTH 33.75' (LEANS SOUTH) CORNER FALLS IN PROJ. OF FENCELINE TO SOUTH CORNER FALLS IN 4' FILL AREA TO NORTH & 2' FILL AREA TO SOUTH SET 5/8" X 24" IRON BAR W/STD. CAP IN MONUMENT BOX IN PLACE OF P.K. NAIL



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 24" IRON BAR W/STD. CAP IN MONUMENT BOX N & W 1.0' HIGH IN SOUTH SIDE OF 24" WALNUT = N61°E 35,96' 1/2" IRON BAR = \$48°E 35,23' N & W 1.0' HIGH IN E. SIDE OF 16" OAK = \$45°W 61.44' N & W 1.0' HIGH IN SW SIDE OF 16" ELM = N35°W 28.54'

RATIFIED BY PEER GROUP IN ACCORDANCE WITH P.A. 345 JULY 10 CO. REPRESENTATIVE

	1	Au		-
Signed by		MU	.W	abla
_				

David W. Mostrom

Date\_ July 19, 2000

Surveyor's Michigan License No.

32339

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 18, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995