LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	St Josejon
1. PUBLIC LAND SURVEY	т. <u>7</u> Š., к. <u>10</u> 🕏.	E-5	STIT
2. PROPERTY CONTROLL- 1NG IN SECTION 1	,T. 7 S., R. 10 V.	E-5	-
3. MISCELLANEOUS PROPERTY IN SECTION	,T N. E. W.		
4. LOT NO , RECO	RDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on 1922, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 1922, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:			
A. Description of original monument and accessories and/or subsequent restoration:			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: Found R.R. Spike This corner is part of the recorded plat of Lake Shore Number One			
C. Description of monument fo	r corner and accessories es	stablished to perpetuate loca	ting the position of the comer:
R.R. Spike			
S. 60° E. 58 S. 50° W. 57 N. 58° E. 57. N. 72° W. 53. N. 22° E. 53. SIGNED BY	30" Hicko Dowck Pol S Powck Pol JO" B. OA	rey le k	arch 31,1972
SURVEYOR'S MICHIGAN REG			(SEAL)
FOR STATE AND UNITED STATES AGENCIES:			
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED BY_	MICHIGAN REGISTERED LAN	DATE	(SEAL)