

JAN 17 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
St. Joseph Located In: Corner Code #
(County)

LIBER 4 PAGE 153

STATE OF MICHIGAN
ST. JOSEPH COUNTY
FILED

19 MAY 95 2:34 P.M.

CYNTHIA JARRATT
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

1. Public Land Survey T Z S R 10W
T R
T R
T R
G-2
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

I, Donald C. Andrews, in a field survey on May, 1995, do hereby certify that under requirements of P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO - Post

LCRC 3, P. 106 1976 PIPE IN MON BOX

LCRC 3, P. 107 PIPE IN MON BOX

VARIOUS SURVEYS USED THE PIPE IN MON BOX AS THE CORNER

P.P. N-26.2'

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2								
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1" TAPPED IRON X 38" LONG IN MON BOX. REMOVED IRON AND MON BOX. FOUND 12"X12" STONE DOWN 4.3 FT. PEER GROUP ACCEPTED STONE AS MARKING THE QUARTER CORNER BETWEEN SECTIONS 3 AND 4.



RATIFIED BY PEER GROUP
IN ACCORDANCE WITH P.A. 345
ON MAY 8, 1995
Wm CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 5/8" IRON X 24" AND ALUMINUM CAP OVER STONE

WITNESS: RR A.P. S42°E 39.80 FT, 17" WHITE PINE S55°W 58.50 FT, POWER POLE N5°W 26.98 FT, RR A.P. N25°W 42.87 FT.

Signed by Donald C. Andrews
Donald C. Andrews, P.S.

Date May 16, 1995

Surveyor's Michigan License No. 33967

REMONUMENTATION