LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1971

For Corners in				LIBER 6 PAGE 35			
ST. JOSEPH	Located In:	Corner Code #		LIDER W	STATE OF		
(County) 1. Public Land Survey	T_7SR_10W_	K-3			ST. JOSEP FILE		
	TR			•	20 APR 2000	9:24:31 AN	
	TR			1	-		
	TR	SURVEY &			CYNTHIA L REGISTER		
2. Property Controlling	STR	MONUMENTATIO	11				
in Section	STR	JAN 31 2001					
3. Miscellaneous	STR	SECTION	Pogisto	or of Doods	Stown 9 Eil	ing Number	
Property in Sec.	S		Registe	or Deeds	Stamp & Fil	ing number	
4. Lot No	_, Recorded Plat			а в с	: N F F (3 HIJKLI	
5. Private Claims				2 6	-5-4-4	3-2-1-	
				3 4 7	1 1		
I, DONALD C. ANDREWS, in a field survey on MARCH 7, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefor as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corners mentioned in lines 3, 4 and 5 above were in conformance with					-8 -9 -	- 10 11 12	
					- 17 16	- 15 - 14 - 13	
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re- established, monument, re-monumented, recovered, found as expressed below:				7 8 - 19 -	-2021	-222324-	
NOTE: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.				9	-2021	-22-23-24-	
				10 30	-5,35,8-	-27-26-25-	
A. Description of original monument and accessories and/or Subsequent restoration:			ation:	12 -3:	-3233-	-343536	
				13			
1880 TODD BK. "A" PG. 3	395 RESET WITH "+" STONE			EY ¾" PIPE	IN MON. BO	X, WIT. SAME AS	
	TONE UNDER MON. BOX	777	Y IN 1981				
AP N39°W 42.6°, PP S4		SURVE	DSTROM SURV Y IN 1981	EY ¾" PIPE	IN MON. BO	X, WIT. SAME AS	
1981 MOSTROM SURVEY PP \$45°E 45.80°, AP No	Y FND %" PIPE IN MON. BOX 53°W 50'		OSTROM SURV	EY ¾" PIPE	IN MON. BO	X	
		PP S	45°E 45.80', AP	N53°W 50',	IRON BAR N	789°01'53"E 33.00'	
B. Description of corne	er evidence found and/or meth	od applied in restoring or r	eestablishing c	omer:			
				O IN CENTERLINE AND CENTERLINE OF CTION OF ROADS			
	ON 5/8" X 12" IN CONCRETE		LOTION OF TO	OADS .			
UP S34°E 45.58°		÷	RATI	FIED BY	PEER GRO CE WITH F	UP .	
			ON	March	<i>13</i> ;	2000	
			113/11	<u>c.</u>	REPRESEN	ITATIVE	
C: Description of monum	ent for corner and accessorie	s to perpetuate locating th	e position of the	e corner:			
	2" IN CONCRETE IN MON	. BOX	أأفع	OF H	Marie		
AP N53°W 49.48' 14" ASH EAST 33.05'			51	(E	W. C.		
UP S45°E 45.58'			1×/	DONALD	c*.\		

UP S45°E 45.58' A.P. S14°E 87.53°

Surveyors Michigan License No. 33967

OFESSION N FORM APPROVED BY MICHIGAN STATE SAND OF LAND SURVORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995
ADAPTED FOR WORD PROCESSING

ANDREWS

PROFESSIONAL SURVEYOR

REMONUMENTATION