

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

St. Joseph

(County)

Fawn River Twp.  
1. Public Land Survey

Located In:

Corner Code #

*Fig 1*

T8S R 9W

I-3

T R

T R

T R

T R

2. Property Controlling  
in Section

S

T R

3. Miscellaneous  
Property in Sec.

S

T R

S

T R

LIBER 5 PAGE 155

STATE OF MICHIGAN  
ST. JOSEPH COUNTY  
FILED

27 APR 1999 1:20:44 PM

CYNTHIA L. JARRATT  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Wayne A. Mostrom, in a field survey on March 24, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1896 Survey in A/725

Mostrom 1977 Survey

Stone & Stake previously set  
White Oak Stump = N73E° 139 lks (91.74')  
16" Yellow Oak = N58 3/4°W 65 lks (42.9')  
7" Maple = N25°E 86 1/3 lks (56.98')

Found 1/2" Pipe over stone  
12" Sycamore = N09°W 63.3'  
10" Oak = N70°W 58.8'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1 1/2" Pipe 16" long on angle over blue/grey +d stone  
Dug 36" below stone - no stake was found  
Centerline E-W gravel roadway = South 1'  
No possession to North or South

RATIFIED BY PEER GROUP  
IN ACCORDANCE WITH P.A. 345  
ON APRIL 19, 1999  
Wayne A. Mostrom CO. REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Removed Stone and Set 5/8" X 24" Bar w/std. cap in mon. box  
N & W in E Side P.P. = N08°E 50.58'  
N & W in S Side 32" Maple = N78°E 111.21'  
N & W in N Side 36" Oak Stump = S75°E 91.87'  
N & W in S Side 22" Cherry = N80°W 163.54'



Signed by Wayne A. Mostrom  
Surveyor's Michigan License No. 14100

Date April 29, 1999

REMONUMENTATION