

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 42-43 N. R. 14W


Schoolcraft COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 6-31

CORNER MONUMENT 1" Pipe with 4" Brass Cap.

DATE MONUMENT PLACED AND WITNESSED 5-23-61

WITNESSES TO CORNER..... 9" Jack Pine (1/4 S NBT) N65°W 09 1/2 links



9" Jack Pine (1/4 S NBT) N83°E 28 links

8" Jack Pine (1/4 S NBT) S31°W 15 1/2 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established by single proportionate measure between two Section Corners. No evidence of original Corner.
Corner lies on Jackpine ridge.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE December 28, 1961