

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. ~~41-42~~ NR. 15 W..

Schoolcraft

..... COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 31, 32, 5, 6 ..

DESCRIPTION OF CORNER MONUMENT 2" iron pipe with 2" brass cap ..

WITNESSES TO CORNER 12" Cedar N 80° E 31½ links
Marked "S 32 N.B.T."

8" Cedar S 65° W 29 links
Marked "S 6 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Re-witnessed pipe as set by Carl Christianson, Manistique.

3" Cedar B.T. in place in good condition.

Placed location poster on old winter road 1/3 Ch. West of Sec. Corner.

Shown to us by Carl Makel, D. F.

Corner re-witnessed January 8, 1957.

SURVEYORS SEAL

SIGNED

Billy D. Buckles
REGISTERED LAND SURVEYOR

DATE 1-11-57