

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

SCHOOLCRAFT CO.

3 CORNERS.

FOR CORNERS OF:-	LOCATED IN:-	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____	T. <u>42</u> N. <u>15</u> W.	<u>C-9, C-10</u>
2. PROPERTY CONTROLLING IN SECTION <u>30</u>	T. <u>42</u> N. <u>15</u> W.	<u>7</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____	T. _____ N. _____ E. _____	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Gerald L. Wiggins, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 10-20-88 & 1-9 & 1, 29 89, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

C-9 N.E. Section Corner of Section 30. OBT'S: Cedar 14, N10°E, 19 lks. & Cedar 12, S20°W, 37 lks.

C-10 East 1/4 Corner of Section 30. OBT'S: 9" Cedar, N43°W, 17 lks. & 12" Cedar, S54°E, 17 lks.

7 North 1/16 Corner on eastside of Section 30. Not previously set.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

C-9 Corner set and witnessed as set by A.O. Enger L.S. #13581, Nov. 19, 1962 from one original bearing tree, a Cedar 12", N10°E, 19 lks.

C-10 This corner set by single proportionate measure between N.E. Corner and S.E. Corner of Section 30. Both Section Corners were set from original evidence.

7 Corner set midpoint on line between N.E. Corner and East 1/4 Corner of Section 30.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
DNR Monument placed at all three corners.

C-9 6" Sq. Cedar, S60°W, 3.35'	C-10 8" Cedar, N37°E, 14.0'	7 8" Cedar, North, 17.7'
10" Cedar, N20°W, 20.6'	8" Cedar, N73°E, 21.9'	8" Cedar, N62°E, 30.1'
5" Cedar, N35°E, 28.95'	10" Cedar, N88°W, 10.95'	8" Cedar, S12°E, 15.8'
6" Cedar, S14°E, 19.65'	5" Cedar, S18°E, 10.1'	10" Scribed Sq. Cedar, with pipe drove on east side.

SIGNED BY Gerald L. Wiggins DATE 2-14-89

SURVEYOR'S MICHIGAN REGISTRATION NO. 23521


FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

MICHIGAN REGISTERED LAND SURVEYOR



(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
REVISED MAY 14, 1978

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET