

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

SCHOOLCRAFT  
(County)

Located In:

Corner Code ##

- |                                    |   |     |   |           |     |
|------------------------------------|---|-----|---|-----------|-----|
| 1. Public Land Survey              | T | 42N | R | 15W       | F-3 |
|                                    | T | 42N | R | 15W       | G-3 |
|                                    | T |     | R |           |     |
|                                    | T |     | R |           |     |
| 2. Property Controlling In Section | S | 1   | T | 42N R 15W | 1   |
|                                    | S |     | T |           |     |
| 3. Miscellaneous Property in Sec.  | S |     | T |           |     |
|                                    | S |     | T |           |     |

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_ Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

I, GERALD L. WIGGINS, in a field survey on 3-5, 6-25, 19 91, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

- A. Description of original monument and accessories and/or subsequent restoration:
- F-3 1/4 Corner between 4 and 9. O.B.T.'S.: Balsam 7, S54°E, 17 lks. & Balsam 6, N60°W, 4 lks.
- G-3 Sec. Corner common to 4,3,9,10. O.B.T.'S.: Cedar 12, S41°E, 14 lks. & Cedar 8, N48°W, 21 lks.
- 1 West 1/16 Corner between Sections 4 and 9. Not previously set.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- F-3 Corner set midpoint on line between N.W. Section Corner and N.E. Section Corner of Section 9.
- G-3 Witnessed corner as set by Carl Christensen in 1950 from original bearing trees, he placed a 2" Iron Pipe with conc. and brass cap.
- 1 Corner set midpoint on line between North 1/4 Corner and N.W. Corner of Section 9.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- F-3 DNR Monument, 10" Maple, N35°E, 9.9' & 6" Y. Birch, N32°W, 10.3' & 8" Y. Birch, S82°W, 23.6' & 8" Maple, South, 12.15'.
- G-3 I.P. Brass cap 6" Cedar, S76°W, 13.4' & 6" Cedar, East, 17.4' & 10" Cedar, N37°E, 21.1' & 8" Cedar, N63°W, 29.3'.
- 1 DNR Monument, 12" Maple, N52°E, 18.35' & 14" Maple, N22°E, 9.85' & 10" Maple, North, 16.65' & 10" Beech, N49°W, 43.3'.

Signed by Gerald L. Wiggins *Gerald L. Wiggins* Date 6-26-91  
 Surveyor's Michigan License No. 23521

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS

