

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Schoolcraft (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 4 T 42N R 15W	1
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 05/06/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

West 1/16 corner between Section 4 T42N-R15W and Section 33 T43N-R15W. 1967 - Established by Frank J. Bray RLS midway and on line between 1/4 corner to east and section corner to west. Set 1" I.pipe with 4" aluminum cap, buried. 10" W.Pine S44E 46 links, 12" W.Pine N31E 216.5 links, wood post east 10 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found the 1967 monument in good condition, at record bearing and distance from the 1967 W.Pine BTs, both in good condition, and substantially at the position of record. Accepted same as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found 1"ID I.pipe with 4" alum. MI Dept. of Conservation cap. Set measuring nail with MDNR tag in the side of:  
22" W.Pine S39E 30.75' mrkd "W1/16 BT" (1967 BT)  
20" W.Pine S74W 17.7' do  
10" W.Pine S70E 25.4' do  
8" J.Pine N31E 48.05' do  
E= 8062372.926 N= 143405.018

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)  
Coord. Ref.=NGS PID DL6164: N= 131822.939 m. E= 8059239.498 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 09/05/2013

For the Michigan Department of Natural Resources, Forest Resources Division

