## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

| 1.                                   | #. K            |                     |  |             |
|--------------------------------------|-----------------|---------------------|--|-------------|
|                                      |                 | Schoolcraft         | <u>.                                    </u> | COUNTY      |
| DESCRIPTION OF CORNER Section Corn   | er fer Sections | 4, 5, 8, and 9      |  |             |
| CORNER MONUMENT 1º Pipe with         | 4" Brazs Cap    |                     |  |             |
| DATE MONUMENT PLACED AND WITHESSED _ | 1/19/61 with    | Bill Wallace a      | nd Art Enger                                 |             |
| NITHESSES TO CORNER 18" Red Pine     | (3 8 MBT)       | S 69 <sup>®</sup> W | 461 Links                                    |             |
| Squared and                          | seribed 16" Red | Pine at Corner      | <u></u>                                      | <del></del> |
| AND                                  |                 |                     |  |             |

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one Spruce Pine B.T., bearing N 46 B, 06 Links in good condition. Found by Art Enger.

SURVEYOR'S SEAL

Billy D. Backler